National Transportation Safety Board FACTUAL REPORT AYIATION

NTSB ID: MIA04WA137 Aircraft Registration Number: HP-1397APP

Occurrence Date: 08/16/2004 Most Critical Injury: Minor

Occurrence Type: Accident Investigated By:

Location/Time

Airport Proximity:	Distance From	n Landing Facility:		Direction Fro	m Airport:
Panama City			0835	EST	
Nearest City/Place	State	Zip Code	Local Time	Time Zone	

Aircraft Information Summary

, morant imprimation Carrinally		
Aircraft Manufacturer	Model/Series	Type of Aircraft
Cessna	C208	Airplane

Sightseeing Flight: No

Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On August 16, 2004, about 0835, eastern standard time, a Cessna 208, Panamanian registration HP-1397APP, registered to and operated by AeroPerla, as an air taxi flight, struck trees during a force landing near Panama City, Panama. Visual meteorological conditions prevailed at the time and flight plan information was not available. The airplane incurred substantial damage. The commercial-rated pilot and the commercial-rated co-pilot along with the five passengers received minor injuries. The flight originated from Marcos A. Gelabert International Airport, Albrook, Panama, about 0830, that morning.

Preliminary information received from the government of Panama indicated the airplane had a loss of engine power minutes after takeoff. The pilot radio the control tower of the situation and attempt to return to the airport. He was unable to reach the airport and elected to perform emergency landing on active road. Due to on coming vehicles the pilot was forced to direct the airplane off to the side of the road were it incurred damage with tress before coming to a stop.

The investigation is under the jurisdiction of the government of Panama. Further information pertaining to this accident may be obtained from:

Departamento Seguridad Aviacion Investigacion Accidente, Panama, Republica de Panama 011-507-315-9102 011-507-315-9134

This report is for information purposes only and contains only information obtained for or released by the Government of Panama.

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: MIA04WA137

Occurrence Date: 08/16/2004

AVIATION	AVIATION Occurrence Type: Accident											
Landing Facility/Approach In	formation											
Airport Name Airp				Airport Eleva	ation t. MSL		Runway Used Runwa			th	Runv	vay Width
Runway Surface Type:												
Runway Surface Condition:												
Type Instrument Approach:												
VFR Approach/Landing:												
Aircraft Information												
Aircraft Manufacturer Cessna			Model C208	I/Series B					Serial	Numbe	er	
Airworthiness Certificate(s):												
Landing Gear Type:												
Homebuilt Aircraft? No	omebuilt Aircraft? No Number of Seats:				Certified Max Gross Wt.				LBS Numbe			:
Engine Type:	Engine Ma	Engine Manufacturer: Model/Series:							Rate	d Power:		
- Aircraft Inspection Information												
Type of Last Inspection Da				Date of Last Inspection Time Sin			nce Last Inspection Hours			Airfrar	Airframe Total Time Hours	
- Emergency Locator Transmitter (ELT) Information											
ELT Installed? ELT Operated? ELT Aided in Locating Accident Site?												
Owner/Operator Information												
Registered Aircraft Owner Street Address												
	City	City State Zi							Zip Code			
Operator of Aircraft Street Address												
Aeroperlas City Panama City										Stat	te	Zip Code
Operator Does Business As: Operator Designator Code:												
- Type of U.S. Certificate(s) Held: I	None											
Air Carrier Operating Certificate(s)	:											
Operating Certificate: Operator Certificate:												
Regulation Flight Conducted Unde	r: Non-U.S., Comr	mercial										
Type of Flight Operation Conducted	d:											
	Ţ	FACTU	JAL REPC	ORT - AVIAT	ION							Page 2

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: MIA04WA137

Occurrence Date: 08/16/2004

AVI	ATIO	Ň		Occurren										
First Pilot Information														
Name City											Sta	te D	ate of Birth	Age
On File														
Sex: Seat Occi	upied:		Prir	ncipal Profes	sion:					Cei	rtificat	e Numbe	er:	
Certificate(s):														
Airplane Rating(s):														
Rotorcraft/Glider/LTA:														
Instrument Rating(s):														
Instructor Rating(s):														
Type Rating/Endorsement for Accident/Incident Aircraft? Current Biennial Flight Review?														
Medical Cert.: Medical Cert. Status:									[Date of La	ast Me	edical Ex	am:	
- Flight Time Matrix		All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Nigh	t	Actual	Instrument Actual Simulated				Glider	Lighter Than Air
Total Time														
Pilot In Command(PIC)											+		-	
Instructor Last 90 Days									-		+		_	
Last 30 Days											+			
Last 24 Hours									\neg		+			
Seatbelt Used? Shoulder Harness Used? Toxicology Performed? Second Pilot?														
	Second Fliot: Second Fliot: Second Fliot: Second Fliot:													
Flight Plan/Itinerary	/													
Type of Flight Plan File		nown												
Departure Point State Airport Identifier Departure Time Time Zone									Time Zone					
								MPMG						
Destination State Airport Identifier														
Chitre														
Type of Clearance:														
Type of Airspace:														
Weather Information	on													
Source of Briefing:														
Method of Briefing:														
FACTUAL REPORT - AVIATION Page 3														

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: MIA04WA137

Occurrence Date: 08/16/2004

Occurrence Type: Accident

	FTYBOR		0000	,,,,,,,	71001001						
Weather	Information										
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF D	WOF Distance From Accident Site			Direction From Accident Site		
			Ft.	MSL			NM	Deg. N			
Sky/Lowes	st Cloud Condition:				<u>!</u>	Ft. AGL	Condition of	Condition of Light:			
							<u> </u>				
Lowest Ce	iling:		Ft.	AGL	Visib	ility:	SM	Altii	meter: "Hg		
Temperatu	Temperature: °C Dew Point: °C Wind Direction: Density Altitude:						nsity Altitude: Ft.				
Wind Spee	ed:	Gusts:		Weath	ner Condt	ions at Accider	nt Site: Visual C	Cond	itions		
Visibility (F	RVR): Ft.	Visibility (R'	VV)	SM	Intensit	y of Precipitation	on:				
Restriction	s to Visibility:										
Type of Pr	ecipitation:										
Accident	Information										
Aircraft Damage: Aircraft F					Aircraft E				n		
Classificati	ion:		•				•				
- Injury Su	mmary Matrix	Fatal Se	rious Mino	or	None	TOTAL					
First Pi	ilot			1		1					
Second	d Pilot			1		1					
Studer	nt Pilot										
Flight I	nstructor										
Check	Pilot										
Flight E	Engineer										
Cabin /	Attendants										
Other (Crew										
Passer	ngers			5		5					
- TOTAL /	ABOARD -			7		7					
Other (Ground										
- GRANI	O TOTAL -			7		7					
			·			•					

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: MIA04WA137

Occurrence Date: 08/16/2004

Occurrence Type: Accident

nistrative	

Investigator-In-Charge (IIC)

Jose L. Obregon

Additional Persons Participating in This Accident/Incident Investigation:

Javier Rodriguez FAA Miami International